

RECEIVING INSPECTION REPORT

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080139-0

No. 11388

RECEIVED FROM

PLANT 19

DATE REC'D. 3/27/59

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO
QUANTITY
RECEIVED

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O ACCT. OR R W.O. NO.	S.O. NO.	REMARKS
322	0	62	0	2						

DRAWING NO. AND DESCRIPTION

732160 Draft Assembly

I.P. A003315

RECEIVED
BY

HMC-104

INSPECTED
BY

DATE

REJECTS RETURNED
ON SHIP. MEMO NO.

3/7/59

RECEIVED FROM

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2961 E. COLORADO ST., PASADENA, CALIF.

No. 11393

DATE REC'D. 3/27/59
P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO
QUANTITY
RECEIVED

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O ACCT. OR R W.O. NO.	S.O. NO.	REMARKS
322	0	7	D	20						

DRAWING NO. AND DESCRIPTION

732177 Pot & Releaser Switch Assembly

I.P. A003314

RECEIVED
BY

HMC-104

INSPECTED
BY

DATE

REJECTS RETURNED
ON SHIP. MEMO NO.

3/7/59

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080139-0